

SENENICH PROPELLER CO., INC.

AREA CODE 813
PHONE - 752-3711
FAX - 752-2818



2008 WOOD COURT
PLANT CITY, FL USA
33563

See us on the Web @ www.sensenich.com

SERVICE BULLETIN SB11-04-15

EFFECTIVE DATE: 4/15/2011

SUBJECT: Rotax Hub Loss of Pitch

AFFECTED PROPELLER HUB MODELS: Hub model used on the Rotax 912/914 series engines.

- 2A0R5

AFFECTED SERIAL NUMBERS: All 2A0R5, revision B Hubs. The revision number can be found following the serial number stamped on the side of the hub.

- Examples – Affected - 21234**B** (Revision B)
Not Affected - 21234, 21234**A**, 21234**C** (Not Revision B)

AFFECTED PUBLICATIONS: N/A

REASON: Sensenich has received reports of pitch loss in a small percentage of 2A0R5 revision B hubs.

- The occurrence, although rare, will result in the propeller blades slowly migrating to a lower pitch setting.

COMPLIANCE: Discontinue flight operation if pitch loss is present and return hub for replacement. If no pitch loss is present, return hub for replacement at earliest convenience.

HUBS NOT AFFECTED: The following is a list of hub models **NOT** affected.

- 2A1R5
- 2A0R5 (non-revision B)
- 2A0J5
- 3A0R5
- 3B0R5
- 2EK, 2EL, 2EM6
- 2G0M7
- 2A2V5