

SENSENICH PROPELLER MANUFACTURING COMPANY, INC.

AREA CODE 717
PHONE - 569-0435
FAX - 560-3725



14 CITATION LANE
LITITZ, PA
17543

November 18th, 2021

Dear Paul,

Thank you for your inquiry with respect to our bolts and the requirements for replacement.

The bolts provided with the propeller can be torqued to the recommended specifications per the logbook with no limitations on the number of installations.

We do recommend replacement if any of the following conditions are met:

- The threads have been damaged or show signs of being stripped.
- The propeller has reached the 2000-hour threshold and is being overhauled.
- The aircraft has experienced a propeller strike that requires repair or adjustment to the propeller tracking or pitch.

Sincerely,

A handwritten signature in blue ink, appearing to read "David Burkhart". The signature is fluid and cursive, written over a white background.

David Burkhart
General Manager / Accountable Manager
Sensenich Propeller Mfg. Co Inc